

# **EXHIBIT JJ**

## **SUPPLEMENT TO HONEY LOCATION FACT REPORT**

### **Supplemental Background Information:**

As part of discovery in civil litigation regarding the October 2017 wildfires, the California Department of Forestry and Fire Prevention ("CAL FIRE") recently produced its Investigation Report, 17CABTU015990-102 (the "CAL FIRE Report"). On May 25, 2018, CAL FIRE issued a press release stating that the Honey Fire was caused by an oak tree branch contacting PG&E powerlines.

PG&E submits the following background information:

The CPUC's designated area of interest is 2484 Honey Run Road in Chico and includes a span of two conductors between two utility poles. A PG&E troubleman observed a broken tree branch in contact with a PG&E conductor at the Honey Fire area of interest during the night of October 9-10, 2017, while assisting CAL FIRE in responding to the Honey Fire.

### **Supplemental Evidence Collection Information:**

PG&E indicated in the Honey Fact Report that PG&E collected two branch sections from a Live Oak from the Honey area of interest, but stated that PG&E did not know whether CAL FIRE collected additional evidence from the area of interest.

In addition, since preparing the Honey Fact Report, PG&E has collected two additional branch sections from the same Live Oak and two overhead conductors.

### **Supplemental Timeline Information:**

The Honey Factual Report contained a timeline of PG&E's actions at or impacting the area of interest in the period immediately preceding CAL FIRE's designated start time until service to the area of interest was restored. The following additional information is relevant to the Honey Factual Report timeline.

- August 15, 2017: The subject tree was trimmed by Utility Tree Service, LLC. PG&E records indicate that trimmers achieved at least twelve feet of clearance between the subject tree and the conductors.
- October 9, 2017, 3:03 PM: CAL FIRE received a 911 call reporting a vegetation fire near 2485 Honey Run Road.

### **Supplemental Information Regarding Prior Inspections:**

Between October 2014 and October 2017, there were six vegetation management inspections at and near the area of interest. PG&E's understanding based upon its records is that the Live Oak tree near 2484 Honey Run Road ("the subject tree") was identified for work once, on July 25, 2017, with the trimming completed on August 15, 2017. There was an electric maintenance overhead inspection at and near the area of

interest on April 24, 2017. PG&E's understanding based upon its records is that no issues were identified with PG&E equipment at the area of interest during that inspection. Below is a summary of vegetation management patrols and inspections and the electric maintenance overhead inspection.

<b>Date</b>	<b>Event</b>	<b>Findings</b>
5/11/2015	Western Environmental Consultants, Inc. ("WECI") performed a vegetation management routine patrol.	PG&E's understanding based upon its records is that the subject tree was not identified for work.
5/6/2016	WECI performed a vegetation management routine patrol.	PG&E's understanding based upon its records is that the subject tree was not identified for work.
8/1/2016–8/2/2016	A PG&E contractor performed a vegetation management aerial Catastrophic Event Memorandum Account ("CEMA") patrol.	PG&E's understanding based upon its records is that the subject tree was not identified for work.
11/3/2016	A PG&E contractor performed a vegetation management aerial Catastrophic Event Memorandum Account ("CEMA") patrol.	PG&E's understanding based upon its records is that the subject tree was not identified for work.
4/24/2017	PG&E performed an electric maintenance overhead inspection.	PG&E's understanding based upon its records is that no issues were identified with PG&E equipment at the area of interest.
7/25/2017	WECI performed a vegetation management routine patrol.	PG&E's understanding based upon its records is that the subject tree was identified for work, and was trimmed by Utility Tree Service, LLC on August 15, 2017.
9/29/2017	WECI performed a vegetation management aerial CEMA patrol.	PG&E's understanding based upon its records is that the subject tree was not identified for work.

**Source List:**

<b><u>Source</u></b>	<b><u>Brief Description</u></b>
CAL FIRE Report	CAL FIRE Investigation Report 17CABTU015990, Honey Fire
CAL FIRE Press Release	CAL FIRE Press Release, "CAL FIRE Investigators Determine Cause of Four Wildfires in Butte and Nevada Counties," May 25, 2018, <a href="https://calfire.ca.gov/communications/downloads/newsreleases/2018/2017_WildfireSiege_Cause%20v2%20AB%20(002).pdf">https://calfire.ca.gov/communications/downloads/newsreleases/2018/2017_WildfireSiege_Cause%20v2%20AB%20(002).pdf</a>
Evidence Log	Spreadsheet showing evidence collected in connection with the North Bay Fires, provided to CPUC on August 15, 2018
PGE-CF_00004926; PGE-CF_00004939	Electric Maintenance Overhead Inspection Records
PGE-NBF-0000020974; PGE-NBF-0000020976	Vegetation Management CEMA Records
PGE-CPUC_00011998	PG&E Annual Vegetation Management Plans
PGE-CPUC_00011399	PG&E Annual Vegetation Management Plans
PGE-NBF-0000021032	Vegetation Management Routine Patrol Record
PGE-NBF-0000020978	Vegetation Management Tree Trimming Record